Work Orde												Page 1
Revision ID:	D3272-1 Step			Accept					Setup	Start Stop		
Start Date: Required Date: Reference:	1/21/11 1/31/11	Start Qty: 10.0 Req'd Qty: 10.0			Cust Item II Customer:) :						8(1) (8) (18) (85)
Approvals:	Process Pla QC:	n: MF	Date: //- *\[D]/	Tooling: SPC (Y/N):	Da			Ì	Run	Start Stop		
Sequence ID/ Work Center II)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp Stamp
Draw Nbr	Rev	ision Nbr										
D3272	Rev	В .		×						•		
100 Large Fab		. Large Fab		0.00	A11	.02 .	A.	/C)	P	200	
Large Fab		1-Cut D		E CUTTING OTHER END** 5.25" long as per Dwg D3272 :				e	and the same		ŕ	
		2-Drill e 3-Debur	Section 2	72 using Jig DT8680 for rivets						-	· -	
	ζ.	QC6- Inspect dimens	ions to drawing	0.00] ,	gr ³ '	L				
QC	-	Memo		0.00	C	DUIC	02.0	9				

Quality Control

Memo

W/O:			V	ORK ORDER CHANGE	S		·		
DATE	STEP	PROC	EDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Dort No.	_	PAR #:	Fault Ca	***************************************	NCD: Voc	No DO		Data	
Part No									
	R	esolution:						Date: _	
NCR:		W	ORK OR	DER NON-CONFORMA		R)			1
DATE	STEP	Description of NC		Corrective Action Section			cation	Approval	Approval
JA12	0,2,	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector
•									İ
									-
			ľ						
		·							
						1			

Work Order ID 65300

Page 2

January 11, 2011 9:20:16 AM

Item ID:

D3272-1

Setup Start

Stop



Revision ID:

Start Date:

Item Name: Step

Required Date: 1/31/11

1/21/11

QC:

Start Qty: 10.00

Req'd Qty: 10.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Accept

Tooling:

SPC (Y/N):

Date:

Date:

Run Start

Stop



Set Up/ **Run Hours**

0.00

Tool ID

Tool # Plan

Code

Accept Qty

Reject Reject Qty Number

Insp. Stamp

120

Sequence ID/

Work Center ID

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location:

Date:

Memo

0.00

130

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Dart Aerospace Ltd	Dart	Aeros	pace	Ltd
---------------------------	-------------	--------------	------	-----

Duit Aci	oopuoc	LU							
W/O:			· W	ORK ORDER CHANGE	ES	<u>-</u>			· \
DATE	STEP	PROC	CEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			200000						
Part No	•	PAR #:	_ Fault Ca	tegory:	NCR: Yes	No DQ	A :	Date:	
	R	esolution:	_ Disposit	ion:	QA: N/C CI	osed:		Date: _	
NCR:		W	ORK OR	DER NON-CONFORMA	NCE (NCR	3)			
	T _	Description of NC		Corrective Action Section	on B	Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ion C	Chief Eng	QC Inspector
· .									
	· .					:			
,									
								í	
								,	

Picklist Print

January 11, 2011 9:20:15 AM

Work Order ID: 65300

Parent Item: D3272-1

Parent Item Name: Step

72-1



Start Date: 1/21/11

Required Date: 1/31/11

Start Qty: 10.00

Required Qty: 10.00

ርሳ	m	m	en	te	•

IPP Rev:A

New Issue 07-06-09 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2622-120C		Manufactured	No			100	Each	17.7000		10	2) 5G	

Step Extrusion

Locat	<u>ion</u>	Loc Qty	Loc Code	
WA	364409	17.7		_10_
	55214	3.42		
	58544	1		
	61208	13.28		

Page 1

Dart Aerospace Ltd	e Ltd
--------------------	-------

W/O:				WORK ORDER	CHANGES					
DATE	STEP		PRO	OCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
•										
Port No	<u> </u>		DAD #.	Fault Category:	NC	P. Voc	No DO	۸.	Date:	
Part NC										
	R	lesolution:		Disposition:	Q <i>P</i>	A: N/C	Closed:		Date: _	
NCR:			,	WORK ORDER NON-COM	NFORMANC	E (NC	R)			

NCR:		1	WORK ORDI	ER NON-CONFORMANO	CE (NCR)			
		Description of NC		Corrective Action Section B		Verification	Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspecto
						!		



DESIG	"P	DRAWN BY	DART AEROSPACE L' HAWKESBURY, ONTARIO, CANADA	.TD
CHEC	(ED	APPROVED	DRAWING NO.	REV. B
	E	世	D3272 s	HEET 1 OF 3
DATE			TITLE	SCALE
07.0	05.18		STEP ASSEMBLY, HI LONG	NTS
Α		04.03.01	NEW ISSUE	
В		07.05.18	D3272-1 WAS D2622-120	

0706 04


QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	Х	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
16	16	MS20600AD4W4	RIVET
1			

GENERAL NOTES:

- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1 POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3 **BLACK ANTI-SKID PAINT PER DART QSI 005 4.4**
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.



W/O:			W	ORK ORDER CHANGI	ES				
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No:		PAR #:							•
Resolution:		Disposition: Q			A: N/C Closed: Date:			-av-	
NCR:		•	WORK ORD	ER NON-CONFORMA	NCE (NC	CR)			
DATE	STEP	Description of NC Section A	Initial				ification ection C	Approval Chief Eng	Approval QC Inspector
,			Chief Eng	Chief Eng	Da	ie			
	:								



봀

DOCUMENT

ឆ

₹

PURPOSE

욹 COPIED

DART


RT AEROSPACE (

A H

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE				у [Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									,		
,											
									;		
							···				
Part No:			PAR #: Fault Category: NC								
Resolution		esolution:	Disposition: Q			A: N/C Closed: Date:					
NCR:		V	VORK ORDE	R NON-CONFORM	IANCE (N	VCR)					
	STED	Description of NC			ction B	: 9	Verific		Approval	Approval	
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sec Action Description Chief Eng	S	ign & Date	Verific Section		Approval Chief Eng	Approval QC Inspector	
	STEP	Description of NC Section A	Initial	Action Description	S	ign & Date				Approval QC Inspector	
	STEP	Description of NC Section A	Initial	Action Description	S	ign & Date				Approval QC Inspector	
	STEP	Description of NC Section A	Initial	Action Description	S	ign & Date				Approval QC Inspector	
	STEP	Description of NC Section A	Initial	Action Description	S	ign & Date				Approval QC Inspector	
	STEP	Description of NC Section A	Initial	Action Description	S	ign & Date				Approval QC Inspector	
	STEP	Description of NC Section A	Initial	Action Description	S	ign & Date				Approval QC Inspector	
	STEP	Description of NC Section A	Initial	Action Description	S	ign & Date				Approval QC Inspector	
	STEP	Description of NC Section A	Initial	Action Description	S	ign & Date				Approval QC Inspector	



DESIGN DRAWN BY		DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA				
CHECKED	APPROVED ,	DRAWING NO.	REV. B			
LE		D3272	SHEET 3 OF 3			
DATE		TITLE	SCALE			
07.05.18		STEP ASSEMBLY, HI LONG	1:20			



Copyright 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:			WO	RK ORDER CHANG	ES			
DATE STEP		PROCEDURE CHANGE			Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			٠.					
				,			,	
			·					
Part No:PAR #:		PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQA :	Date: _	
		esolution:	Disposition	n:	_ QA: N/C Clo	osed:	Date:	
NCR:		\	WORK ORD	R NON-CONFORM	ANCE (NCR)		
DATE	STEP	Description of NC	Corrective Action Section			Verification	Approval	Approval
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
		·						
						·		
	i							
l	1						İ	